LIST OF TABLES

Table 1. 1: The chemical compositions of few nickel base superalloys (wt.%).....**4**

Table 1. 2: Role of different alloying elements in Ni-base superalloys **6**

Table 1. 3: Typical chemical composition of superalloy IN718 (wt.%). **8**

Table 2. 1: Chemical composition of the superalloy IN718 (wt.%). **30**

Table 3.1: Visual observation of the samples oxidized/hot corroded at 600ºC up to 100 h **48**

Table 3.2: Parabolic rate constant (k_p) of the samples with different roughness, corroded at 600^0C up to 100 h. **51**

Table 3. 3: The phases formed on the samples corroded by 1S, 2SM and 3SM at 600ºC, up to 100 h of exposure **56**

Table 3.4: Parabolic rate constant (k_p) of the non USP and USP treated samples, corroded at 600^0C up to 100 h. **64**

Table 4.1: Visual observation of the samples oxidized hot corroded at 700ºC up to 100 h. **80**

Table 4.2: Parabolic rate constant (k_p) of the samples with different roughness, corroded at 700^0C up to 100 h. **83**

Table 4.3: Parabolic rate constant (k_p) of the non USP and USP treated samples, corroded at 700ºC up to 100 h. **88**

Table 5.1: HCF test data of the as heat treated specimens tested at 600ºC, at cyclic frequency of 30 Hz at R= -1. .....**101**

Table 5.2: HCF test data of the pre hot corroded specimens tested at 600ºC, at cyclic frequency of 30 Hz at R= -1. .....**102**

Table 5.3: High cycle fatigue parameters derived from Basquin relationship. **102**

Table 5.4: Rate of fatigue crack propagation of the superalloy IN718 in different condition **105**

Table 6.1: Comparison of actual and calculated values of the stress amplitudes at different mean stresses corresponding to R = 0.5 and 0.7 for 10^6 cycles……**119**