

# CONTENTS

---

---

<b>Chapters</b>	<b>Title</b>	<b>Page No.</b>
	Certificates	<b>ii-iv</b>
	Acknowledgements	<b>v-vi</b>
	Contents	<b>vii-x</b>
	List of Figures	<b>xi-xiv</b>
	List of Tables	<b>xv</b>
	<i>Preface</i>	<b>xvi-xviii</b>
<b>Chapter – 1</b>	<b>INTRODUCTION</b>	<b>1-9</b>
	1.1 Introduction	1
	1.2 Background and motivation	3
	1.3 Research Objectives	6
	1.4 The benefit to society	7
	1.5 Thesis structure	8
<b>Chapter – 2</b>	<b>LITERATURE REVIEW</b>	<b>10-31</b>
	2.1 Introduction	10
	2.2 Channel pattern	11
	2.3 Channel pattern controls	11
	2.4 River metrics	14
	2.4.1 Sinuosity	15
	2.4.2 River Network Change Index (RNCI)	16
	2.4.3 Radius of curvature	17
	2.4.4 Centerline migration rate	19
	2.5 Extreme flood events	21
	2.6 Frequency of floods	21
	2.7 Fluvial erosion model	23
	2.8 Physically-Based (PB) method for migration	24
	2.9 Meander migration	25
	2.10 Models of meander migration	26
	2.11 Types of models	27
	2.12 RVR meander model	29
	2.13 Summary	31
<b>Chapter- 3</b>	<b>STUDY AREA</b>	<b>32-42</b>
	3.1 Introduction	32
	3.2 Land use/ land cover	34
	3.3 Climate	37

	3.4 Geology	37
	3.5 Soil type	39
	3.6 Hydrodynamics	41
	3.7 Summary	42
<b>Chapter – 4</b>	<b>DECADAL CHANNEL PLANFORM DYNAMICS</b>	<b>43-72</b>
	4.1 Introduction	43
	4.2 Data	46
	4.3 Methodology	47
	4.3.1 Controlling for Discharge	47
	4.3.2 Georectification	48
	4.3.3 Controlling the Variation in Spatial Resolution	50
	4.3.4 Vectorization of river planform	51
	4.3.5 Channel shifting	51
	4.4 Results	54
	4.4.1 Channel morphology and topographic analysis	54
	4.4.2 Centerline migration	59
	4.4.3 Planform Dynamics in Segment A	61
	4.4.4 Planform Dynamics in Segment B	64
	4.5 Discussions and Conclusions	71
<b>Chapter -5</b>	<b>SAR DATA BASED ASSESSMENT OF CHANNEL PLANFORM DURING MONSOON</b>	<b>73-94</b>
	5.1 Introduction	73
	5.2 Data	78
	5.3 Methodology	79
	5.4 Results and discussion	81
	5.4.1 Hydrological observations	81
	5.4.2 Validation of SAR data classification	84
	5.4.3 Flood monitoring	85
	5.4.4 Pre and post-flood observation in Ganga and Ramganga doab	88
	5.4.5 Effects of an extreme flood on Ramganga river morphology	89
	5.5 Conclusion	91

<b>Chapter – 6</b>	<b>HYDROLOGICAL EVENTS EFFECTS ON CHANNEL PLANFORM</b>	<b>95-125</b>
	6.1 Introduction	95
	6.2 Data used	100
	6.3 Methodology	101
	6.4 Results geomorphological evolution	104
	6.4.1 Width of the active channel	104
	6.4.2 Radius of curvature	105
	6.4.3 Sinuosity index	107
	6.4.4 Channel migration	108
	6.4.5 Morphological evolutions of meander loops	109
	6.5 Flood Frequency Analysis	114
	6.5.1 Log-Pearson Type III (LP3)	114
	6.6 Hydrology and geomorphology	118
	6.7 Discussion	123
	6.7.1 Geomorphological evolution	123
	6.7.2 Hydrology and Geomorphology	124
	6.8 Conclusion	125
<b>Chapter- 7</b>	<b>PREDICTIVE MODELLING OF CHANNEL PLANFORM</b>	<b>126-154</b>
	7.1 Introduction	126
	7.2 Data	131
	7.2.1 Discharge	131
	7.2.2 Soil	131
	7.2.3 Satellite image	131
	7.3 Model Inputs	132
	7.3.1 Design of bankfull discharge	132
	7.3.2 Channel dimensions such as width, depth, and slope	132
	7.3.3 Critical shear stress	132
	7.3.4 Erosion-rate coefficient	132
	7.3.5 Soil texture determination in laboratory	133
	7.3.6 Unit weight	134
	7.3.7 Shear strength of a soil	134
	7.3.8 Initial section properties	135
	7.4 Methodology	136
	7.4.1 Model Description	136

	7.4.2 Model calibration	137
	7.5 Results and discussion	140
	7.5.1 Scenario 1: Prediction of planform for 100 years	140
	7.5.2 Scenario 2: Impact of climate change on the Ramganga river	143
	7.5.3 Impact on rural settlement	145
	7.6 Model Sensitivity Analysis and Limitations	151
<b>Chapter-8</b>	<b>CONCLUSION AND FINDINGS</b>	<b>155-165</b>
	8.1 Introduction	155
	8.2 Specific conclusion	156
	8.2.1 Chapter 4	156
	8.2.2 Chapter 5	157
	8.2.3 Chapter 6	159
	8.2.4 Chapter 7	161
	8.3 Limitation of the research	163
	8.4 Scope for future research	164
	<b>REFERENCE</b>	<b>166-194</b>
	<b>Appendix A- Yearly maximum discharge data</b>	<b>195</b>

## LIST OF FIGURE

<b>Figure No.</b>	<b>Title</b>	<b>Page No.</b>
Figure 1.1	(a) Eroded village and (b) Eroded bank along the Ramganga river	5
Figure 2.1	Diagram representing the calculation of the Sinuosity index for the single-channel	15
Figure 2.2	Plan-view sketch of idealized river meander (redrawn after Williams, 1986)	19
Figure 2.3	Determination of channel migration rate based on Shields JR et al.,( 2000)	20
Figure 2.4	Schematic view of different model types for simulating river systems. A: hydrological; B: floodplain inundation; C: channel evolution; D: alluvial stratigraphy; E: meandering, (based on Van De Wiel et al., 2011)	28
Figure 2.5	RVR Meander software is available as a stand-alone program for MS Windows and Linux operating systems and as a plugin for ESRI's ArcMap (based on Eddy J. Langendoen et al., 2015.)	31
Figure 3.1	Study area showing the lower course of Ramganga and its tributary and distributary	33
Figure 3.2	Distribution of land use/ land cover in Ramganga Basin based on Landsat -8 data	35
Figure 3.3	Land use/ Land cover map of the Ramganga river basin based on Landsat-8 data	36
Figure 3.4	Geological map of study area based on the geological survey of India map (54M)	38
Figure 3.5	Soil map of the Ramganga basin (Source: NRSC (2005))	40
Figure 3.6	Annual average hydrograph of Ramganga river (Data source: CWC, 2018)	41
Figure 4.1	Monthly average discharge for three months plotted against the year from 1985 to 2018 for the Ramganga river at Dabri hydrological station (Data Source: CWC, 2019)	48
Figure 4.2	SRTM DEM of the Study Area.	53
Figure 4.3	Temporal changes of sinuosity in the upstream area.	54
Figure 4.4	Temporal changes of sinuosity in the downstream area	55

Figure 4.5	Topographic profiles extracted from SRTM DEM (vertical error < 4 m) along the selected sections (AB, BC, and CD).	56
Figure 4.6	Longitudinal profile of a segment of Ramganga river of old (Gambhiri river) and new course (Kunda nala).	57
Figure 4.7	Channel configuration in the lower course of Ramganga river	58
Figure 4.8	River Centerline dynamics in two Segment over a 237-year period.	60
Figure 4.9	Systematic reconstruction of Planform dynamics in Segment A for the period 1780 to 2017 (Miyan Patti-M <sub>p</sub> , Garhi Aurangabad-Ga, Rulapur-Ru, Auranga Bad-Ab, Kundauli-K, RatanpurPamaran-Rp, Rajepur-Rj, KamaluddeenPur-Kp, Ramapur Patti-R, Barhaulti-B)	63
Figure 4.10	Systematic reconstruction of Planform dynamics in Segment B for the period 1780 to 1922 (Patti Palpur-Pp, Shyampur-S, Bari-B, Kurhar-K, Chaunsar-C, Umrauli Jaitpur-Uj, Ram Nagar-Rn, Rabiyaapur-R, Mastapur-M, Naunpurwa-Np).	64
Figure 4.11	Systematic reconstruction of Planform dynamics in Segment B for the period 1773 to 1990 (Patti palpur-Pp, Shyampur-S, Bari-B, Kurhar-K, Chaunsar-C, UmrauliJaitpur-Uj, Ram Nagar-Rn, Rabiyaapur-R, Mastapur-M, Naunpurwa-Np)	65
Figure 4.12	Systematic reconstruction of Planform dynamics in Segment B for the period 1990 to 2010 (Patti palpur-Pp, Shyampur-S, Bari-B, Kurhar-K, Chaunsar-C, UmrauliJaitpur-Uj, Ram Nagar-Rn, Rabiyaapur-R, Mastapur-M, Naunpurwa-Np).	67
Figure 4.13	Systematic reconstruction of Planform dynamics in Segment A for the period 2010 to 2017 (Patti palpur-Pp, Shyampur-S, Bari-B, Kurhar-K, Chaunsar-C, UmrauliJaitpur-Uj, Ram Nagar-Rn, Rabiyaapur-R, Mastapur-M, Naunpurwa-Np).	68
Figure 4.14	(a) Field photographs showing fluvial deposition during major flood events with layers provide clues about recent fluvial dynamics, (b) Severe erosion of left bank near the village Barhaulti. The black arrow shows the direction of present-day flow.	69

Figure 4.15	Field photographs showing the abandoned channel of Gambhiri Naddi and width of the channel indicates flow conditions in the past (b) Left bank erosion around the confluence of Ganga and Ramganga rivers	70
Figure 5.1	Location of flood effected reaches in Ramganga River	77
Figure 5.2	Methodology used in the study	79
Figure 5.3	Flood hydrograph for the Ganga river at Fatehgarh and Dabri gauge stations from 5 August 2018 to 28 September 2018	82
Figure 5.4	Percentage of the inundated area in Ganga and Ramganga doab	83
Figure 5.5	Validation of the results for the region with the Sentinel-2, MNDWI image in which green representing water for 14-SEP-2018, (A) Sentinel-1 SAR image for 14-SEP-2018, VV polarization (B), VH polarised SAR image (C).	85
Figure 5.6	Temporal inundation area maps based on Sentinel- 1 data	86
Figure 5.7	Temporal inundation area maps based on Sentinel- 1	87
Figure 5.8	Sentinel-2 image of 2018 and during-flood Sentinel-2 image of 14 September 2018 showing changes in the course of the Ganga and Ramganga river. Triangle in yellow colour represents the location of Gauge Stations.	88
Figure 5.9	Active channel before and after the flood	90
Figure 6.1	Location of different mender loops in segment A and segment B	99
Figure 6.2	Methodology used in the study	103
Figure 6.3	Active channel width evolution and its trend	104
Figure 6.4	Evolution of curvature radius during 1973-2019	105
Figure 6.5	Temporal measurement of radius of curvature of meander 12.	106
Figure 6.6	Evolution of sinuosity index in study reach	107
Figure 6.7	Channel migration during five periods in study area	108
Figure 6.8	Model of meander change based on Hooke (1984)	110
Figure 6.9	Morphological evolutions in some meander loops in the Ramganga River	111
Figure 6.10	Morphological evolutions in some meander loops in the Ramganga River	112
Figure 6.11	Annual average and peak discharge during study period based on CWC data	119

Figure 6.12	Correlation between frequency of hydrological events and geomorphological evolution in the study reach for $Q > Q_2$	121
Figure 6.13	Correlation between frequency of hydrological events and geomorphological evolution in the study reach for $Q > Q_5$	122
Figure 7.1	Map showing the highly dynamic Baran meander and location of bridge on Ramganga river	130
Figure 7.2	Soil texture classification	133
Figure 7.3	Comparison between historic and modelled 2000 channel centerlines of the Ramganga river.	138
Figure 7.4	Comparison between historic and modelled 2010 channel centerlines of the Ramganga river	139
Figure 7.5	RVR Meander output showing migrated centerlines at 10-year increment	142
Figure 7.6	RVR Meander output showing migrated centerlines at 10-year increments with increased flow	144
Figure 7.7	Rural settlements which are prone to erosion	148
Figure 7.8	Endangered houses, trees, and farms due to severe bank erosion of concave side of bends	149
Figure 7.9	Severe bank erosion with fracturing and collapse of bank	150
Figure 7.10	Soil sample collection using Shelby tube sampler in the field	153
Figure 7.11	Soil texture analysis in the lab using Hydrometer test.	154

## LIST OF TABLE

<b>Table No.</b>	<b>Title</b>	<b>Page No.</b>
Table 4.1	Spatial data source	47
Table 4.2	Classification of channel pattern.	52
Table 5.1	Data source	78
Table 5.2	OA, PA, UA accuracies and kappa coefficient ( $\kappa$ ) for validation	84
Table 5.3	Morphological Characteristics of Ramganga river before and after Flood	92
Table 5.4	Morphological characteristics of Ramganga in meander scale	92
Table 6.1	List of spatial data and hydrological data sources	100
Table 6.2	Frequency of meanders change in different type of evolution In Segment A	113
Table 6.3	Frequency of meanders change in different type of evolution In Segment B	113
Table 6.4	Computation of statistical parameters for Dabri gauge station	116
Table 6.5	Flood frequency estimates of Ramganga river using Log Pearson Type III distribution (Dabri station)	117
Table 6.6	Frequency of different recurrence interval discharges in study periods (flood day per year)	120
Table 6.7	Results of Pearson correlation test between frequency of hydrological events and geomorphological evolution	120
Table 6.8	Correlation between frequency of hydrological events and geomorphological evolution in the study reach	120
Table 7.1	List of input parameter for RVR Meander Model	136
Table 7.2	List of the village which is highly prone to erosion in the next 100 years	145